



**1187 Wilmette Avenue, Suite 133**  
**Wilmette, Illinois 60091**  
**T: 847-716-7369 F: 847-716-7367**  
**www.acmproducts.com**



## **ACM-4 and ACM-5 Cut Off Saw Parts List**

**Prices in Effect 04/21/10; Subject To Change Without Notice**

<b>PART #</b>	<b>DESCRIPTION</b>	<b>QUANTITY</b>	<b>PRICE</b>
B-102	Saw Base (Does not include V-block or clamp)	1 each	\$195.50
B-107	Adjustable stop	1 each	\$4.50
B-121	Dowel pin for P-101	1 set (2 each)	\$4.50
B-123	Set screws for B-102	1 set (2 each)	\$2.50
B-125	Rubber mounts (feet) for B-102	1 set (4 each)	\$2.50
B-131	Dowel pin for B-132	1 each	\$1.75
B-132	V-block	1 each	\$115.50
B-133	Toggle clamp	1 each	\$30.50
B-150	Spindle for B-133 (toggle clamp)	1 each	\$3.50
B-153	Return spring (attaches between P-101 & B-102)	1 each	\$5.50
D-103	Spindle Assembly (Complete with Bearings)	1 each	\$127.50
D-104	Spindle nut (Locks D-109 to D-103)	1 each	\$6.50
D-105	Four-inch wheel guard/retainer plate	1 each	\$125.50
D-106	Five-inch wheel guard/retainer plate	1 each	\$125.50
D-109	Wheel flanges, 1/2 square arbor (male & female)	1 set (2 each)	\$56.50
D-113	Drive belt, geared, glass cord	1 each	\$14.95
D-114	Pulley, motor drive (includes set screws)	1 each	\$25.50
D-116	Pulley, spindle drive (includes set screws)	1 each	\$30.50
D-118	Belt guard spacers	1 set (2 each)	\$6.50
D-126	Belt guard	1 each	\$52.50
D-128	Safety Shield, transparent	1 each	\$15.50
D-137	Mounting bracket for D-128	1 each	\$7.50
D-143	Spindle bearing	1 set (2 each)	\$15.50
D-148	Spindle shaft (without bearings)	1 each	\$105.50
D-154	Handle knob for D-105	1 each	\$2.50
M-112B	Motor, 230V 1/2 HP; Totally enclosed	1 each	\$545.50
M-112C	Motor, 115V 1/2 HP; Ventilated (open-end)	1 each	\$395.50
M-112D	Motor, 115V 1/2 HP; Totally enclosed	1 each	\$455.50
M-138	Motor brush plate	1 each	\$10.50
M-139	Motor brush retainer springs	1 set (2 each)	\$2.50
M-140	Motor fan	1 each	\$11.50
M-142	Motor brushes	1 set (2 each)	\$15.50
M-145	Power cord, 6 feet (complete with on/off switch)	1 each	\$45.50
M-147	Motor bearing (brush end)	1 each	\$9.50
M-149	Motor bearing (fan end)	1 each	\$11.50
P-101	Pivot Base; Motor support (Does not include Spindle)	1 each	\$195.50
P-108	Handle shaft	1 each	\$10.50
P-120	Handle knob	1 each	\$7.50